Certificate Number UL-US-L16383-21741-81204102-2

Report Reference EX16383-20140218

Date 30-Aug-2023

Issued to: Ningjin APC Industries Incorporated Company

18 OF TAISHAN RD

NINGJIN, Shandong Sheng 253400

China

This is to certify that representative samples of

HLXS - Butterfly Valves

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL/ULC 1091, Edition: 7, Issue Date: 2022-4-20


Additional Information: See the UL Online Certifications Directory at

https://iq.ulprospector.com for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.





Certificate Number UL-US-L16383-21741-81204102-2

Report Reference EX16383-20140218

Date 30-Aug-2023

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
GD-381X	Butterfly Valve
HFGD-381X	Butterfly Valve
HFGD-381X-175	Butterfly Valve
HFGD-381Y	Butterfly Valve
HFGD-381Y-175	Butterfly Valve
HGD-381X	Butterfly Valve
HGD-381X-175	Butterfly Valve
HGD-381Y	Butterfly Valve
HGD-381Y-175	Butterfly Valve
WD-371X	Butterfly Valve

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/



Certificate Number UL-CA-L16383-21761-81204102-2

Report Reference EX16383-20140218

Date 30-Aug-2023

Issued to: Ningjin APC Industries Incorporated Company

18 OF TAISHAN RD

NINGJIN, Shandong Sheng 253400

China

This is to certify that HLX representative samples of

HLXS7 - Butterfly Valves Certified for Canada See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/CAN/UL/ULC 1091:2022, Edition: 7, Issue Date:

2022-4-20

Additional Information: See the UL Online Certifications Directory at

https://ig.ulprospector.com for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Debrah Jennings-Course

U

Deborah Jennings-Conner, VP Regulatory Services

Certificate Number UL-CA-L16383-21761-81204102-2

Report Reference EX16383-20140218

Date 30-Aug-2023

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
GD-381X	Butterfly Valve
HFGD-381X	Butterfly Valve
HFGD-381X-175	Butterfly Valve
HFGD-381Y	Butterfly Valve
HFGD-381Y-175	Butterfly Valve
HGD-381X	Butterfly Valve
HGD-381X-175	Butterfly Valve
HGD-381Y	Butterfly Valve
HGD-381Y-175	Butterfly Valve
WD-371X	Butterfly Valve

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

